




A RICE LAKE WEIGHING SYSTEMS COMPANY

## DFWL PLUS • DFWLI PLUS





# HOME TABLE OF CONTENTS

---

<b>1. Introduction and warnings</b>	<b>4</b>
<b>2. Technical features</b>	<b>5</b>
<b>3. Approval</b>	<b>6</b>
<b>4. Connections</b>	<b>7</b>
Single-channel	7
Multichannel	8
<b>5. Programming</b>	<b>9</b>
How to access the programming menu	9
How to save the programming and exit the menu	9
Programming menu	10
<b>6. Communication strings</b>	<b>44</b>
<b>7. Communication commands</b>	<b>49</b>
<b>8. Wiring diagrams</b>	<b>51</b>
CPU board	51
232 serial port with RJ11 connector	51
Optional IN/OUT DFIO board	51
Optional analogue DAC16OSER output board	52
<b>9. Programming errors</b>	<b>53</b>
<b>10. Summary of the parameters</b>	<b>54</b>
<b>11. FAQ - Frequently asked questions</b>	<b>57</b>

## CONTENTS BY TOPIC

---

<b>Calibration</b>	
Quick calibration	11
Complete calibration	40
<b>Equalisation</b>	
Multi-channel connection	8
Equalisation procedure	39
<b>Safety</b>	
Protection of the configuration menu via PIN	43
Protection of the user menu via PIN	43
<b>Communication</b>	
Configuration of the serial port for PC	13
Configuration of the serial port for printer	15
Wiring diagrams	50
Communication strings	44
Communication commands	49
<b>Approval</b>	
Approval seal	6
Viewing the metrological version	6
<b>Reset</b>	
Factory configuration reset	36
Complete memory reset	43

# 1. INTRODUCTION AND WARNINGS

This product is the best solution for multi-function weighing applications, offering ease of use, high precision in reading the weight, and many functions to speed up and simplify everyday work.

This manual provides an overview of the potentials of the product. The configuration menu can be used to adapt the product functionality to the required weighing application.




## WARNINGS:

- Do not make repairs or replace electronic components of the instrument boards.
- Only use original spare parts.
- Any tampering with the equipment or use of non-original spare parts voids the warranty and relieves the manufacturer of any liability.
- Before any installation or repair that involves access to electronic parts, turn off the device and disconnect any source of power supply (battery, 230V network or other).
- Always use network power supply sources regulated within  $\pm 10\%$  of the rated voltage.
- In applications in connection with third parties, always follow the specifications given on the approval decree of the equipment.
- Do not immerse in water.
- Do not wash with water jets (except versions with specific IP protection degree).
- Protect from direct rainfall (except versions with specific IP protection degree).
- Do not use aggressive cleaning solvents or substances.
- Do not install in potentially explosive environments.
- Earth connect any earth socket located on the equipment casing, using a cable with a diameter of at least 16 mm<sup>2</sup>.

## 2. TECHNICAL FEATURES


	DFWL PLUS	DFWLI PLUS
<b>Case</b>	ABS	AISI 304 stainless steel
<b>Screen</b>	Backlit LCD digit height = 25 mm	
<b>Brightness</b>	5 intensity levels	
<b>Keypad</b>	5 keys, waterproof	
<b>IP protection rating</b>	-	IP68
<b>Cable gland</b>	Standard	1 PG9, plastic
	Extra	-
<b>Load cell inputs</b>		4
<b>Number of scales</b>		1
<b>Maximum number of connectable load cells</b>		8 x 350 Ω
<b>Maximum input current to load cells</b>		120 mA
<b>Temperature range</b>	Internal use	-10°C /+40°C
	Type-approved	-10°C /+40°C
<b>Power supply</b>	<i>Battery</i>	4 x AA
	<i>Battery duration</i>	up to 40 h
	<i>Power supply</i>	External IN: 110/240 Vac OUT: 12 Vdc
	<i>Available plugs</i>	EU, AU, UK, US
<b>Serial ports</b>	<i>RS232</i>	1 (RJ11 connector)
	<i>RS232 + CTS</i>	1 (internal, not usable)
	<i>RS485</i>	1 (internal, not usable)
	<i>TTL</i>	1 (internal, not usable)
	<i>Sensor</i>	1 (internal, not usable)
	<i>USB</i>	1 Mini-USB (internal, for manufacturer use only)
<b>Number of divisions</b>	<i>Internal use</i>	from 100 to 800,000
	<i>Type-approved</i>	10,000 / 3 x 3,000
<b>Digital outputs (DFIO, optional)</b>	<i>Max. number</i>	6  48 Vac or 60 Vdc 15 mA 10 Ω Max
	<i>Features</i>	
<b>Digital inputs (DFIO, optional)</b>	<i>Max. number</i>	2  12 / 24 Vdc 5 / 20 mA
	<i>Features</i>	
<b>Analogue output (DACP16OSER, optional)</b>	<i>Voltage</i>	0 / 5 V    0 / 10 V    -5 / 5 V    -10 / 10 V  0 / 20 mA
	<i>Current</i>	

### 3. APPROVAL




#### How to display the metrological version of the instrument


##### 1. Turn off the scale



##### 2. Follow the procedure:




## 4. CONNECTIONS




### Single-channel

Connect the scale to the main terminal block using the first reading channel of the A/D converter.



### Reference terminal block for 1-channel connection




#### NOTES:

- For 6-wire connection with "Sense", set the dip switches to OFF.
- For 4-wire connection, set the dip switches to ON.



#### WARNING:


Make connections with indicator off and power supply disconnected.  
Comply with the electronic specifications indicated in the table on page 4



### Multi-channel with digital equalisation

The 4 channels of the converter can be used to connect 2, 3 or 4 cells, digitally equalising them without using junction boxes.


### Reference terminal blocks for 4-channel connection




## 5. PROGRAMMING

### How to access the programming menu

#### 1. Turn off the scale




#### 2. Follow the procedure:



### How to save the programming and exit the menu


To save the programming changes made, press button **C** repeatedly while navigating the menu backwards, until the message **SAUEP** appears: press **⊖** to save or **C** to exit without saving.

Example (read from right to left):





## PROGRAMMING MENU



Parameter visible only under certain conditions.



Parameter or menu subject to approval.


**MENU**

How to enter

1. Off
2. On
3.   
*(i) Page 9*

How to browse

- =
- =
- =
- =

How to save and exit




*(i) Page 9*


**CAL Quick calibration**

Start of the calibration procedure:

**A-1**



Set the division and press

*How to set the value*



**CAPAC**

Set the capacity and press

*How to set the value*



-oh-

Enter the calibration weight and press


*How to set the value*



**LoAd**

-oh-

**CAL.oF**



**unLoAd**

**CAL.oF**

If an advanced calibration was performed previously, step **CAL** will lead directly to steps **Q-1** **Q-2** **Q-3**.  
(See page 37)

## How to enter

1. Off   
 2. On   
 3.   
 (i) Page 9





## How to browse

- ↑ =   
 ↓ =   
 → =   
 ← = 

## How to save and exit




(i) Page 9


- A** 
- B** 
- C** 
- D** 
- E** 
- F** 
- G** 
- H** 
- I** 
- J** 
- K** 
- L** 
- M** 
- N** 
- O** 
- P** 
- Q** 

**D.CAL** Zeroing the pre-tare


Acquisition of the zero point

**GrAU** Area of gravity of the place of use

Once the calibration is completed, for proper operation set the area of use in this pitch (if different from that of calibration).




How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	




## SERIAL Configuration of the serial ports

### Conn.PC Communication with PC, PLC or Repeater

Selection of the communication mode




Selection of the protocol:




For available protocols see page 44.


**MENU**


How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	Page 9




COM port selection for PC / PLC connection



Communication speed (Baud rate)




Configuration of the serial protocol




 MENU

How to enter	How to browse	How to save and exit
1. Off 	↑ = 	
2. On 	↓ = 	
3. 	→ = 	
 Page 9	← = 	 Page 9




**CoNPrn** Communication with printer or repeater or PC

Selection of the communication mode




Selection of the protocol:




 For available protocols see page 44.

Communication speed (Baud rate)





**MENU**


How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	Page 9




Configuration of the serial protocol



Printer control signal




Printer power supply / Radio-frequency module





**MENU**


How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	


**RuH.1 - RuH.2 Auxiliary ports**

Selection of the communication mode




Selection of the protocol:




For available protocols see page 44.

Communication speed (Baud rate)




# MENU

How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	



Configuration of the serial protocol



uSb USB port


For manufacturer use only.


**MENU**


How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	


**AdUAnC Advanced configurations**


Connection port of radio-frequency module (for use by the manufacturer)




TTL port / inclinometer activation (for use by the manufacturer)



Closing character of each print line



Ignore unknown commands



When an unknown command is sent:  


- Selecting NO will result in the response "ERR04".
- Selecting YES ignores the command (no response).

How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	Page 9


- A CAL
- B D.CAL
- C GrAU
- D SERIAL
- E LAYOUT
- F FILEER 1 LANG
- G SCREEN 2 CHAR
- H BATT 3 HEADER
- I ECOBAT 4 DATA
- J AUTOFF 5 WEIGHS
- K RENOTE 6 CREATE
- L ROUT 7 CLOCK
- M INPUTS 8 BARCODE39
- N OUTPUT 9 BARCODEUP
- O RESET 10 BARCODECL
- P DRG 11 BARCODECH
- Q ADUARNC 12 BARCODEDT
- 13 COPIES
- 14 ENDIC
- 15 BLINIE
- 16 LABEL
- 17 LB.SAVE
- 18 ESE

## Layout Print customisation



Parameters for ticket/label mode




Additional parameters for label mode




# MENU



Print language settings



Font dimensions





**MENU**


How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
<i>(i) Page 9</i>	← =	<i>(i) Page 9</i>

- A **CAL**
- B **0.CAL**
- C **GrAU**
- D **SERIAL**
- E **LAYOUT**
- F **FILEEr** ① **LAyOut**
- G **SCREEn** ② **ChAr**
- H **bATT** ③ **HEAdEr**
- I **ECObATT** ④ **dATA** ① **EnAbLE**
- J **AutoOFF** ⑤ **BE DAtS** ② **L inE 1**
- K **rENote** ⑥ **E CReEt** ③ **L inE 2**
- L **An.out** ⑦ **ClOCH** ④ **L inE 3**
- M **inPutS** ⑧ **BARC.39** ⑤ **L inE 4**
- N **outPut** ⑨ **BARC.uP**
- O **rESEt** ⑩ **BARCL**
- P **d.RG** ⑪ **BARCh**
- Q **AdUAnC** ⑫ **BARC.dt**
- ⑬ **CoP.iES**
- ⑭ **End.E.iC**
- ⑮ **b.L inE**
- ⑯ **LABEL**
- ⑰ **Lb.SAve**
- ⑱ **EESt**

Enables header printing



Contents of the header lines



Enter the first character

Enter the second character

Enter the last character

How to set the value



or

*(i)* Repeat the operation to program L inE 2, L inE 3 and L inE 4. Select no to disable them.


**MENU**

How to enter

1. Off
2. On
- 3.
- (i) Page 9*


How to browse

- ↑ =
- ↓ =
- =
- ← =


How to save and exit


*(i) Page 9*
**A**
**B**
**C**
**D**
**E**
**F**
**1**
**G**
**2**
**H**
**3**
**I**
**4**
**1**
**J**
**5**
**2**
**K**
**6**
**3**
**L**
**7**
**4**
**M**
**8**
**5**
**N**
**9**
**O**
**10**
**P**
**11**
**Q**
**12**
**13**
**14**
**15**
**16**
**17**
**18**

How to print / delete the row being programmed



Programming example



How to set the value


 or  
① ... ⑨

(\*) List of characters


32		47	/	62	>	77	M	92	\	107	k	122	z
33	!	48	0	63	?	78	N	93	]	108	l	123	{
34	"	49	1	64	@	79	O	94	^	109	m	124	
35	#	50	2	65	A	80	P	95	_	110	n	125	}
36	\$	51	3	66	B	81	Q	96	'	111	o	126	~
37	%	52	4	67	C	82	R	97	a	112	p		
38	&	53	5	68	D	83	S	98	b	113	q		
39	'	54	6	69	E	84	T	99	c	114	r		
40	(	55	7	70	F	85	U	100	d	115	s		
41	)	56	8	71	G	86	V	101	e	116	t		
42	*	57	9	72	H	87	W	102	f	117	u		
43	+	58	:	73	I	88	X	103	g	118	v		
44	,	59	;	74	J	89	Y	104	h	119	w		
45	-	60	<	75	K	90	Z	105	i	120	x		
46	.	61	=	76	L	91	[	106	j	121	y		


**MENU**


How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	Page 9

- A **CAL**
- B **OCAL**
- C **GrAU**
- D **SErIAL**
- E **LAyout**
- F **FILEEr** 1 **LAyO**
- G **SCREEn** 2 **ChAr**
- H **bArE** 3 **HEAdEr**
- I **ECo.bAr** 4 **DATA**
- J **AutoOFF** 5 **BE.ihs**
- K **rENote** 6 **E.iCREt**
- L **An.out** 7 **CLoCF**
- M **inPutS** 8 **barC.39**
- N **outPut** 9 **barC.uP**
- O **rESEt** 10 **barC.L**
- P **d.iRG** 11 **barC.h**
- Q **AdUAnC** 12 **barC.dt**
- 13 **CoP.iES**
- 14 **End.E.iC**
- 15 **b.L.inE**
- 16 **LABEL**
- 17 **Lb.SAVE**
- 18 **EESt**


Selection of the weight data



Progressive weighed



Ticket/label progressive





**MENU**

How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	Page 9


- A **CAL**
- B **0.CAL**
- C **GrAU**
- D **SErIAL**
- E **LAYOUT**
- F **FILEEr** 1 **LAyOut**
- G **SCREEn** 2 **ChAr**
- H **bARt** 3 **HEAdEr**
- I **ECo.bAT** 4 **dATA**
- J **AutoOFF** 5 **BE.0H5**
- K **rENoteE** 6 **tICRET**
- L **An.out** 7 **CLoCH**
- M **inPutS** 8 **bArC.39**
- N **outPut** 9 **bArC.uP**
- O **rESEt** 10 **bArC.L**
- P **d.RG** 11 **bArC.h**
- Q **AdUAnC** 12 **bArC.dt**
- 13 **CoP.iES**
- 14 **End.t.iC**
- 15 **b.L.inE**
- 16 **LABEL**
- 17 **Lb.SAUE**
- 18 **EESt**




Date and time




Bar code 39




Barcode top margin (mm)



Barcode left margin (mm)



Barcode height (mm)





**MENU**

How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	Page 9


- A **CAL**
- B **O.CAL**
- C **GrAU**
- D **SEr.iAL**
- E **LAYOUT**
- F **FILEEr** 1 **LAyO**
- G **SCrEEEn** 2 **ChAr**
- H **bArE** 3 **HEAdEr**
- I **ECo.bAr** 4 **dArA**
- J **AutoOFF** 5 **BE.iDHS**
- K **rENote** 6 **E.iCREEt**
- L **An.out** 7 **ClOCH**
- M **inPutS** 8 **bArC.39**
- N **outPut** 9 **bArC.uP**
- O **rESEt** 10 **bArC.L**
- P **d.iRG** 11 **bArC.h**
- Q **AdUAnC** 12 **bArC.dt**
- 13 **CoP.iES**
- 14 **End.e.iC**
- 15 **b.L.inE**
- 16 **LABEL**
- 17 **Lb.SAVE**
- 18 **EESt**

Selection of the weight data


Visible only if **bArC.39** (E-8) is active




Multi-copy prints



Paper outlet for end of ticket/receipt



White print head preheating line (thermal printer only)




# MENU

How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	Page 9


- A CAL
- B LOCAL
- C GrAU
- D SERIAL
- E LAYOUT
- F FILEER 1 LANG
- G SCREEN 2 CHAR
- H BATT 3 HEADER
- I ECOBAT 4 DATA
- J AUTOFF 5 BEADS
- K RENOTE 6 CREATE
- L ROUTER 7 CLOCK
- M INPUTS 8 BARCODE39
- N OUTPUT 9 BARCODEUP
- O RESET 10 BARCODE1D
- P DRG 11 BARCODE1D
- Q ADUARNC 12 BARCODE1D
- 13 COPIES
- 14 ENDIC
- 15 BLINE
- 16 LABEL
- 17 LBSAVE
- 18 TEST

Label configuration


Only visible if Node (D-2-1) = LABEL



Saving labels in printer memory (only for label mode)



Test print ALL FORMATS



How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	Page 9

- A CAL
- B D.CAL
- C GrAU
- D SERIAL
- E LAYOUT
- F FILTER
- G SCREEN 1
- H BATT 2
- I ECO.BAT 3
- J AutoFF 4
- K RENOTE 5
- L AN.out 6
- M INPUTS 7
- N OUTPut 8
- O rESEt 9
- P d.RG 10
- Q AdUARnC 11 CuStoN

## FILTER Weighing filters



To change the responsiveness of the scale.

This is useful to adjust the scale according to your needs.

*With an approved instrument, it is not possible to change the filter.*



### Foreword:

"F 10" represents the lowest filtering incidence.

By increasing the incidence, the weight becomes more stable.

It is advisable to carry out several weighing operations by changing the incidence until the best compromise between responsiveness and stability is achieved.

F 1 Filter at 5 Hz.

F 2 Filter at 10 Hz.

F 3 Filter at 20 Hz.

F 4 Filter at 40 Hz.

F 5 Filter at 80 Hz.

F 6 Filter at 160 Hz.

F 7 Filter at 325 Hz.

F 8 Filter at 650 Hz.

Only visible if n.ChRn < 3

F 9 Filter at 1300 Hz.

Only visible if n.ChRn < 2

F 10 Filter at 2600 Hz.

Only visible if n.ChRn < 2

CuStoN For use by the manufacturer.

# MENU


How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	

- A
- B
- C
- D
- E
- F
- G
- H 1
- I 2
- J 3
- K 4
- L
- M
- N
- O
- P
- Q




## SCREEn Adjusting the display


### Backlighting




### Brightness



### Display lock (for use by the manufacturer)



### Backlight colour




**MENU**
**How to enter**


1. Off 
2. On 
3. 
- (i)* Page 9


**How to browse**

- ↑ = 
- ↓ = 
- = 
- ← = 

**How to save and exit**

*(i)* Page 9

**bA**t**t Battery power supply**

**WARNING:**
*use only original rechargeable batteries.*
**E**C**o.**b**A**t**t Energy saving for battery operation**

*Visible only if bA**t**t (H) is active*


# MENU

## How to enter

1. Off
2. On
- 3.
- (i) Page 9*

## How to browse

- ↑ =
- ↓ =
- =
- ← =


## How to save and exit




*(i) Page 9*

- A **CAL**
- B **0.CAL**
- C **GrAU**
- D **SErIAL**
- E **LAYOUT**
- F **FILEEr**
- G **SCrEEEn**
- H **bATT**
- I **ECobAT**
- J **AutoFF**
- K **rENote**
- L **An.out**
- M **inPutS**
- N **outPut**
- O **rESEt**
- P **d.RG**
- Q **AdUAnC**

## AutoFF Auto switch-off



## rENote Remote control



*(i) The broadcast mode allows sending the control to multiple scales simultaneously.*

How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	


- A
- B
- C
- D
- E
- F
- G
- H
- I
- J
- K
- L
- M 1
- N 2
- O 3
- P 4
- Q 5   
6   
7   
8   
9   
10

## An.out Analogue output




~~Only visible when the optional analogue board is present.~~

Selecting the COM port



Operation proportional to net/gross weight



L-3 Analogue value for weight in underload (0...65535)

L-4 First linearisation weight value (-99999...999999)

L-5 Analogue value related to BGe.1 (0...65535)

L-6 Second weight value of linearisation (-99999...999999)

L-7 Analogue value related to BGe.2 (0...65535)

L-8 Third weight value of linearisation (not mandatory) (-99999...999999)

L-9 Analogue value related to BGe.3 (not mandatory) (0...65535)

L-10 Analogue value relative to weight in "overload" (0...65535)

Using the real time update of the output, it is possible to check the entered value with a tester (see example on page 33).



## MENU

### How to enter

1. Off
2. On
- 3.

### How to browse

- =   
 =   
 =   
 =

### How to save and exit




Page 9


- A **CAL**
- B **0.CAL**
- C **GrAU**
- D **SEr.iAL**
- E **LAYOUT**
- F **FILEEr**
- G **SCrEEEn**
- H **bATT**
- I **ECo.bAT**
- J **AutoOFF**
- K **rENote**
- L **An.out**
- M **inPutS**    1 **CoN**
- N **outPut**    2 **nET**
- O **rESEt**    3 **Pnt.und**
- P **d.iAG**    4 **HGT.1**
- Q **AdUAnC**    5 **Pnt.1**
- 6 **HGT.2**
- 7 **Pnt.2**
- 8 **HGT.3**
- 9 **Pnt.3**
- 10 **Pnt.outr**

### Programming example:

the analogue output provides 10V to program a linearisation point so that at 1000kg.





Enter **62300** (the reference value given in the table) and check the analogue output using a tester.



Adjust the analogue output by increasing or decreasing the value.

Minimum variations of at least 10 points are recommended, (**623 10**, **62320**, **62330**, etc.)

### How to set the value




Once the desired adjustment has been made, confirm the value with .

# MENU

How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	Page 9


- A
- B
- C
- D
- E
- F
- G
- H
- I
- J
- K
- L
- M
- N 1
- O 2
- P
- Q



Value to be entered	Output volts	mA output
1200	~ 0 V	~ 0 mA
11250		~ 4 mA
52200		~ 20 mA
62300	~ 10 V	

## inPutS Digital inputs

### Input configuration 1



Repeat the same operation for .


**MENU**
**How to enter**

1. Off 
2. On 
3. 
- (i)* Page 9

**How to browse**

- ↑ = 
- ↓ = 
- = 
- ← = 

**How to save and exit**


*(i)* Page 9

**A** **CAL**
**B** **O.CAL**
**C** **GrAU**
**D** **SEr.iAL**
**E** **LAyout**
**F** **FILEEr**
**G** **SCrEEEn**
**H** **bAtt**
**I** **ECo.bAt**
**J** **AutoFF**
**K** **rENoteE**
**L** **An.out**
**M** **inPutS**
**N** **outPut**
**O** **rESEt** 
**P** **d.iRG** 
**Q** **AdUAnC** 




**outPut** Digital outputs

Operation on net weight, gross weight or batching



**For dosing / filling:**

- Activate mode **doSAGE**
- Set tare **unLoCF**.

The output is activated only after the container has been calibrated (by key or external button) and is deactivated when the set target (setpoint) is reached. To carry out two-speed filling, two outputs must be programmed with **doSAGE** mode.




 Normally open operation (**n.o.**) or closed (**n.c.**)


Output activation mode



Direct, stable or unstable weight

Only at stable weight


 Double threshold operation  
(activation weight threshold ≠ from output deactivation weight threshold)

**Operation:**
**YES** (Double threshold)

**NO** (Single threshold)

**OFF -> ON**

*(i)* Repeat the same operation for **rEL.b.2**, **rEL.b.3**, **rEL.b.4**, **rEL.b.5** and **rEL.b.6**.

How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	

- A CAL
- B OCAL
- C GrAU
- D SERIAL
- E LAYOUT
- F FILEER
- G SCREEn
- H BATT
- I ECO.BAT
- J AutoFF
- K rENote
- L An.out
- M inPutS
- N outPut
- O rESEt
- P d.iG
- Q AdUAnC
  - 1 AdC.uU
  - 2 d.iSPLA
  - 3 KEYb
  - 4 CTS
  - 5 outPut
  - 6 inPutS
  - 7 An.out
  - 8 SER.nuN
  - 9 PrG.UER
  - 10 d.iU.int
  - 11 AdC.Pnt
  - 12 bt.AdC
  - 13 Ph.AdC
  - 14 SER.iRL

## rESEt Factory configuration reset



Function for restoring default configurations keeping the stored calibration.

## d.iG Diagnostics

- P-1 AdC.uU Converter. Check of input signal in µV. In case of multiple equalised channels, press buttons or to examine all the channels selected.
- P-2 d.iSPLA Display. Integrity check of all segments and icons.
- P-3 KEYb Keypad. Press any key to check its correct operation, with beep and code on display.
- P-4 CTS CTS. Check of status of the control signal from the printer.
- P-5 outPut Optional digital outputs. Check the activation and deactivation of each contact.  
*Example: out 1 activates output 1. Press button to select the next output.*  
**WARNING:** before entering the step *outPut* check that the activation of the output does not cause conditions of danger to persons, animals or property.
- P-6 inPutS Optional digital inputs. Check the activation and deactivation of each input.  
*Example: i.b 1-0 input not active  
Example: i.b 1-1 active input  
Press button to select the next input.*
- P-7 An.out Analogue output. Enter the digital value and check the analogue output response with a tester.
- P-8 SER.nuN Scale serial number.
- P-9 PrG.UER Reviewing hardware (e.g. *rEU 5*) followed by software version (e.g. *04.00.00*).
- P-10 d.iU.int Number of internal divisions.
- P-11 AdC.Pnt Converter. Checking signal in ADC points. In case of multiple equalised channels, press buttons or to examine all the channels selected.
- P-12 bt.AdC Battery voltage value.
- P-13 Ph.AdC Mains power supply voltage value.
- P-14 SER.iRL Scale serial number.

 MENU


How to enter	How to browse	How to save and exit
1. Off 	↑ = 	
2. On 	↓ = 	
3. 	→ = 	
<a href="#">(i) Page 9</a>	← = 	<a href="#">(i) Page 9</a>

- A **CAL**
  - B **D.CAL**
  - C **GrAU**
  - D **SEr.iAL**
  - E **LAYOUT**
  - F **FILEEr**
  - G **SCrEEEn**
  - H **bAtt**
  - I **ECo.bAt**
  - J **AutoFF**
  - K **rENote**
  - L **An.out**
  - M **inPutS**
  - N **outPut**
  - O **rESEt**
  - P **d.iAG**
  - Q **AdUAnC**
- Q-1 **CAL.PAr**
- 1 **CAL.PAr**
  - 2 **EquAL.P**
  - 3 **CAL.Adu**
  - 4 **Stb.FL**
  - 5 **PERAFL**
  - 6 **NEtroL**
  - 7 **AEYb**
  - 8 **ELT**
  - 9 **rEACE**
  - 10 **LoCH.Rb**
  - 11 **AL\_ib.i.r**
  - 12 **P.in.tEC**
  - 13 **P.in.uSE**
  - 14 **dFLt.E**
-  


**AdUAnC Advanced**

**CAL.PAr Calibration parameters** 


Configuration of the decimal point (0...3)



Reading division




Unit of measure



# MENU

How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	



Scale capacity. Set Max or Range 1 (Max range = 800.000)




Range 2

For multirange scales, set the second weighing range.



Range 3


For multirange scales, set the third weighing range.



Example of multirange configuration at 1500/3000 kg, division 0,5/1 kg.


Set:  
 $dEC\_1 = 0.0$   
 $d.iU = 5$   
 $rAnGE\_1 = 15000$   
 $rAnGE\_2 = 30000$

Equalisation function



Connection diagram on page 8.  
Equalisation procedure on page 39.

Equalised analogue channels



How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	Page 9

A

B

C

D

E

F

G

H

I

J

K

L

M

N

O

P

Q







- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14

**EQuAL.P Equalisation**

**EQuAL.P** is only visible if the function **EQuAL** (Q-1-7) is activated in the menu **CAL.PAr** (Q-1).

The equalisation wizard asks to acquire the zero point with scale unloaded and to later place a weight of about 1/8 of the maximum capacity (Max) on each individual cell in the required order. The message **E9.of** will appear after the procedure.

Proceed with the calibration.




How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	Page 9

- A CAL
- B D.CAL
- C GrAU
- D SERIAL
- E LAYOUT
- F FILEER
- G SCREEN
- H BATT
- I ECOBAT
- J AutoFF
- K RENOTE
- L An.out
- M INPUTS
- N outPut
- O rESEt
- P d.AG
- Q AdUAnC
  - 1 CAL.PAr
  - 2 EQUAL.P
  - 3 CAL.Adu
  - 4 Stb.FLT
  - 5 PEAR.FL
  - 6 METROL
  - 7 AEYb
  - 8 ILT
  - 9 rFACE
  - 10 LoCH.Rb
  - 11 AL\_ib\_ir
  - 12 P\_in.BEC
  - 13 P\_in.uSE
  - 14 dFLT.E

## CAL.Adu Complete calibration

Before calibrating, configure the decimals ( - Q-1-1), the division ( - Q-1-2) and the capacity ( - Q-1-4,5,6).

Start of the calibration procedure:



## Stb.FLT Additional stability filter

**Q-4** Stb.FLT For use by the manufacturer.

How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	Page 9

- A CAL
- B CAL.PAR
- C GrAU
- D SERIAL
- E LAYOUT
- F FILEER
- G SCREEn
- H BATT
- I ECO.BAT
- J AutoOFF
- K rENote
- L An.out
- M inPutS
- N outPut
- O rESEt
- P d.RG
- Q AdUAnC
  - 1 CAL.PAR
  - 2 EQUAL.P
  - 3 CAL.Adu
  - 4 Stb.FLT
  - 5 PEAR.FL
    - 1 O.PErC
  - 6 NEtroL
  - 7 AEyb
  - 8 Er.IE
  - 9 rEACT
  - 10 LoCH.Rb
  - 11 AL\_ib\_ir
  - 12 P\_in.EC
  - 13 P\_in.uSE
  - 14 dFLTE.E
- 6 CAL.Adu
- 7 CAL.NAn
- 8 d.SALE

## PEAR.FL Anti-peak filter

Q-4 PEAR.FL For use by the manufacturer.

### NEtroL Metrological parameters

Resetting percentage using the key

Q-5-1 d.iUSb 02 0.5ErH With approved scale (0...2)  
With non-approved scale (0...50)


Sensitivity of the weight stability control

Q-5-2 d.iUSb 02 0.5ErH (0...99)

Stability detection time

Q-5-3 Er.IE 500 0.5ErH With approved scale (500)  
With non-approved scale (10...10000)

Zero hold function (tracking)



Zero tracking speed


Q-5-3 0.5ErH.SP 1000 on.2ErH With approved scale (1000)  
With non-approved scale (100...5000)

# MENU


How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
<i>Page 9</i>	← =	<i>Page 9</i>

- A **CAL**
  - B **0.CAL**
  - C **GrAU**
  - D **SEr.iAL**
  - E **LAyout**
  - F **FILEEr**
  - G **SCrEEEn**
  - H **bATT**
  - I **ECo.bAT**
  - J **AutoFF**
  - K **rENoteE**
  - L **An.out**
  - M **inPutS**
  - N **outPut**
  - O **rESEt**
  - P **d.iAG**
  - Q **AdUAnC**
- 1 **CAL.PAr**
- 2 **EQvAL.P**
- 3 **CAL.Adu**
- 4 **Stb.FLt**
- 5 **PEAr.FL**
- 6 **NETrol**
- 7 **KEYb**
- 8 **t.iLT**
- 9 **rEACE**
- 10 **LoCH.Rb**
- 11 **AL\_ib.i.r**
- 12 **P.in.tEC**
- 13 **P.in.uSE**
- 14 **dFLt.E**
- 1 **OPErC**
- 2 **d.iUSb**
- 3 **t.iLT**
- 4 **0.trf**
- 5 **0.trfSP**
- 6 **on.2Ero**
- 7 **CAL.Adu**
- 8 **CAL.NAn**
- 9 **d.SALE**

Reset at power and reset percentage



Re-acquisition / change of the calibration points in memory.




*i* Repeat the same operation for Po int 1, Po int 2 and Po int 3


**Q-5-8** **CAL.NAn** For use by the manufacturer.

**Q-5-9** **d.SALE** For use by the manufacturer.

Type of keypad



Inclinometer (for use by the manufacturer)




# MENU


How to enter	How to browse	How to save and exit
1. Off	↑ =	
2. On	↓ =	
3.	→ =	
Page 9	← =	

- A CAL
- B D.CAL
- C GrAU
- D SERIAL
- E LAYOUT
- F FILEER
- G SCREEn
- H bATT
- I ECOBAT
- J AutoOFF
- K rENoteE
- L An.out
- M inPutS
- N outPut
- O rESEt
- P d.RG
- Q AdUAnC
  - 1 CAL.PAr
  - 2 EQUAL.P
  - 3 CAL.Adu
  - 4 Stb.FLT
  - 5 PERF.FL
  - 6 NETrol
  - 7 AEYb
  - 8 EILT
  - 9 rEACE
  - 10 LoCH.Rb
  - 11 AL\_ib\_ir
  - 12 P.in.EEC
  - 13 P.in.uSE
  - 14 dFLt.E


Reactivation of the print or weight totalisation function




Permanent keypad lock (excluding key C)



Reset of fiscal memory (alibi memory, optional)



Access PIN to programming menu



Access PIN to user menus

Q-12 P.in.uSE See P.in.EEC

Total reset of memory and of calibration, with reset of the factory settings.



## 6. COMMUNICATION STRINGS

### Short string

**01ST,GS, 0.0,kg<CR><LF>**

where

<b>01</b>	Code 485 of the instrument (2 characters), only if communication mode 485 is enabled
<b>ST</b>	Scale status (2 characters): <u>US</u> - Unstable weight <u>ST</u> - Stable weight <u>OL</u> - Weight overload (out of range) <u>UL</u> - Weight underload (out of range) <u>TL</u> - Scale not level (inclinometer active)
,	ASCII 044 character
<b>GS</b>	Type of weight data (2 characters) <u>GS</u> - Gross <u>NT</u> - Net
,	ASCII 044 character
<b>0.0</b>	Weight (8 characters including the decimal point)
,	ASCII 044 character
<b>kg</b>	Unit of measurement (2 characters)
<b>&lt;CR&gt;&lt;LF&gt;</b>	Transmission terminator, characters ASCII 013 and ASCII 010

### Extended string

**011, ST, 0.0,PT 20.8, 0,kg<CR><LF>**

where

<b>01</b>	Code 485 of the instrument (2 characters), only if communication mode 485 is enabled
<b>1</b>	ASCII 049 character
,	ASCII 044 character
<b>ST</b>	Scale status (2 characters): <u>US</u> - Unstable weight <u>ST</u> - Stable weight <u>OL</u> - Weight overload (out of range) <u>UL</u> - Weight underload (out of range) <u>TL</u> - Scale not level (inclinometer active)
,	ASCII 044 character
<b>0.0</b>	Net weight (10 characters including the decimal point)
,	ASCII 044 character
<b>PT</b>	Indication of pre-set manual tare (2 characters)
<b>20.8</b>	Tare weight (10 characters including the decimal point)
,	ASCII 044 character
<b>0</b>	Number of pieces (10 characters)
,	ASCII 044 character
<b>kg</b>	Unit of measurement (2 characters)
<b>&lt;CR&gt;&lt;LF&gt;</b>	Transmission terminator, characters ASCII 013 and ASCII 010

## Custom string

Foreword:

The configuration can only be carried out using DiniTools in the “CUSTOM STRING FORMATTING” section.

The maximum length of the string configuration field is 100 characters. Fixed alphanumeric characters or variable macros may be used inside.

There are also “tokens” that define the characters that a variable (<>) will become in the string when the indicator is in weighing mode.

The custom string can be composed using the macros on page 49

The default custom string setting is shown below:

<2><P><W7.><U><M><S><CR><LF>

where

<2>	ASCII STX character (start of text)
<P>	Weight polarity
<W7.>	Weight (formatted to 7 digits with decimal point)
<U>	Unit of measure
<M>	Type of weight (gross, net, tare)
<S>	Weight status
<CR><LF>	Transmission terminator, characters ASCII 013 and ASCII 010

Default token:

Gross mode token “<M>”	G
Net mode token “<M>”	N
Tare mode token “<M>”	T
Preset weight token “<M>”	T
Unit token “<U>”	K
Positive polarity token “<P>”	SPACE
Negative polarity token “<P>”	-
Invalid status token “<S>”	I
Motion status token “<S>”	M
Valid status token “<S>”	SPACE
Coz status token “<S>”	Z
Overload status token “<S>”	O
Underload status token “<S>”	O
Overload char token “<S>”	&
Underload char token “<S>”	=

The default command to be sent to the weight indicator to request the custom string is:

nnSF#1<CR><LF>

Available Macro:

Macro	Format	Description	Token value (standard)
Weight sign	<P> <PG> <PN> <PT>	Sign of the displayed weight Sign of the gross weight Sign of the net weight Sign of the tare	The string will show the character set in tokens:  Positive polarity token "<P>" Negative polarity token "<P>"  "SPACE" if the weight is positive "-" if the weight is negative
Unit of measure	<U>		The string will show the character set in token:  Unit token "<U>"
Weight type	<M> <MG> <MN> <MT>	Displayed weight Gross weight Net weight Tare	The string will show the character set in tokens:  Gross mode token "<M>" Net mode token "<M>" Tare mode token "<M>" Preset tare weight token "<M>"  "G" if the weight is gross "N" if the weight is net "T" if the weight is a tare "T" if the weight is a preset tare
Weight status	<S>		The string will show the character set in tokens:  Invalid status token "<S>" Motion status token "<S>" Valid status token "<S>" Coz status token "<S>" Overload status token "<S>" Underload status token "<S>" Overload char token "<S>" Underload char token "<S>"  "I" if the weight is not valid "M" if the weight is not stable "SPACE" if the weight is valid "Z" if the weight is equal to zero "O" if the weight is in overload "O" if the weight is in underload "&" if the weight is in overload, all the weight digits are replaced by & "=" if the weight is in underload, all the weight digits are replaced by =
Weight value	<W-0x.y> <w-0x.y> <G-0x.y> <g-0x.y> <N-0x.y> <n-0x.y> <T-0x.y> <t-0x.y>	Displayed weight [left align      ] Displayed weight [      right align] Gross weight [left align      ] Gross weight [      right align] Net weight [left align      ] Net weight [      right align] Tare [left align      ] Tare [      right align]	The string will show the weight. Depending on the parameters set, the format will change accordingly:  - Show the sign "-" if the weight is negative 0 Fills the empty spaces with "0" x Indicates the number of digits by which the weight is shown (max 15, from 1 to F) - Show the decimal point (If present in the weight) y Indicates the fixed number of digits after the decimal point (If the decimal point is present)  - , 0, -, y characters are optional.
Bit sequence	<Bn,Bn,...>	Indicate a sequence of exactly 8 bits	See bit table
ASCII character	<X>		Add the ASCII character. "CR" and "LF" are recognised as ASCII character 13 and 10 <CR> add the carriage return <LF> add the line feed <2> add the STX character

Bit:

<b>Bit</b>	<b>Bit used</b>	<b>Type</b>	<b>Name</b>	<b>Description</b>
<b>B0</b>	1	Fixed	Bit value = 0	Used to complete the byte
<b>B1</b>	1	Fixed	Bit value = 1	Used to complete the byte
<b>B3</b>	1	Variable	Net weight	1 if the displayed weight is net 0 if the displayed weight is gross
<b>B4</b>	1	Variable	Weight equals to zero	1 if the gross weight is equal to zero (zero indication on the screen) 0 if the gross weight is not equal to zero (no zero indication on the screen)
<b>B5</b>	1	Variable	Stable weight	1 if the weight is stable (no motion indication on the screen) 0 if the weight is unstable (motion indication on the screen)
<b>B6</b>	1	Variable	Negative gross weight	1 if the gross weight is negative 0 if the gross weight is positive
<b>B7</b>	1	Variable	Weight in underload / overload	1 if the weight is in underload / overload 0 if the weight is not in underload / overload
<b>B9</b>	1	Variable	Active tare	1 if a tare is active 0 if there isn't a tare active
<b>B10</b>	1	Variable	Active preset tare	1 if a preset tare is active 0 if there isn't a preset tare active
<b>B11</b>	2	Variable	Weight type	00 if the displayed weight is gross 01 if the displayed weight is net 10 if the displayed weight is a tare

Example of custom string configuration to replicate the standard Dini Argeo string:

<u>String definition</u>	1,<S>,<M>,<P><W7>,<U><CR><LF>
Gross mode token "<M>"	GS
Net mode token "<M>"	NT
Tare mode token "<M>"	T
Preset tare weight token "<M>"	PT
Unit token "<U>"	Depending on the unit of measure
Positive polarity token "<P>"	SPACE
Negative polarity token "<P>"	-
Invalid status token "<S>"	SPACESPACE
Motion status token "<S>"	US
Valid status token "<S>"	ST
Coz status token "<S>"	ZR
Overload status token "<S>"	OL
Underload status token "<S>"	UL
Overload char token "<S>"	(null)
Underload char token "<S>"	(null)

Example of custom string configuration to replicate the extended Dini Argeo string:

<u>String definition</u>	1,<S>,<WA>,<MT><TA>,<U><CR><LF>
Gross mode token "<M>"	GS
Net mode token "<M>"	NT
Tare mode token "<M>"	SPACESPACE
Preset tare weight token "<M>"	PT
Unit token "<U>"	Depending on the unit of measure
Positive polarity token "<P>"	SPACE
Negative polarity token "<P>"	-
Invalid status token "<S>"	SPACESPACE
Motion status token "<S>"	US
Valid status token "<S>"	ST
Coz status token "<S>"	ZR
Overload status token "<S>"	OL
Underload status token "<S>"	UL
Overload char token "<S>"	(null)
Underload char token "<S>"	(null)

## 7. COMMUNICATION COMMANDS

Foreword:

in the serial commands and the respective responses

<b>nn</b>	Address 485 of the instrument (2 characters), only if communication mode 485 is enabled
<CR>	ASCII terminator character 13 (0D) (1 character)
<LF>	ASCII terminator character 10 (0A) (1 character)

### Simple weight reading

<b>Command</b>	<b>nnREAD&lt;CR&gt;&lt;LF&gt;</b>
<b>Response</b>	Short string (see page 44)

### Complete weight reading

<b>Command</b>	<b>nnREXT&lt;CR&gt;&lt;LF&gt;</b>
<b>Response</b>	Long string (see page 44)

### Reading custom string

<b>Command</b>	<b>SF#1&lt;CR&gt;&lt;LF&gt;</b>	(configurable from Dinitools)
<b>Response</b>	String (see page 45)	

### Performing a semi-automatic tare

<b>Command</b>	<b>nnTARE&lt;CR&gt;&lt;LF&gt;</b>
<b>Response</b>	OK<CR><LF> indicates that the command has been received correctly

### Setting a tare value (PT)

<b>Command</b>	<b>nnTMAnnnnnnn&lt;CR&gt;&lt;LF&gt;</b>
	Where n...n is the tare value, with decimal points, max 8 characters.
<b>Response</b>	OK<CR><LF> indicates that the command has been received correctly
<b>Examples</b>	<b>TMAN1.56&lt;CR&gt;&lt;LF&gt;</b> sets a tare value of 1.56
	<b>TMAN100&lt;CR&gt;&lt;LF&gt;</b> sets a tare value of 100

### Clearing the stored tare

<b>Command</b>	<b>nnCLEAR&lt;CR&gt;&lt;LF&gt;</b>
<b>Response</b>	OK<CR><LF> indicates that the command has been received correctly

### Zeroing the scale (ZERO key function)

<b>Command</b>	<b>nnZERO&lt;CR&gt;&lt;LF&gt;</b>
<b>Response</b>	OK<CR><LF> indicates that the command has been received correctly

## SPECIFIC COMMANDS FOR ALIBI MEMORY (OPTIONAL)

### Save requests


<b>Command</b>	<b>nnPID&lt;CR&gt;&lt;LF&gt;</b> request to save the weighing
<b>Response</b>	successful registration <b>nnPIDss,c,wwwwwuu,pppttttttuu,xxxxx-yyyyy&lt;CR&gt;&lt;LF&gt;</b>
	no registration <b>nnPIDss,c,wwwwwuu,pppttttttuu,NO&lt;CR&gt;&lt;LF&gt;</b>
where:	
<b>ss</b>	weight status (2 characters)
<b>TL</b>	<i>L</i> <i>U</i> <i>L</i> error condition (NO RECORDING)
<b>OL</b>	<i>U</i> <i>E</i> <i>R</i> <i>L</i> <i>A</i> <i>R</i> condition (NO RECORDING)
<b>UL</b>	Underload condition (NO REGISTRATION)
<b>ST</b>	Stable weight
<b>US</b>	Unstable weight (NO RECORDING)
<b>c</b>	Scale number (1 character)
<b>w...w</b>	Gross weight (10 characters)
<b>uu</b>	Unit of measurement (2 characters)
<b>pp</b>	Type of tare: double space “ “ if semi-automatic, “PT” if preset (2 characters)
<b>t...t</b>	Tare value (10 characters)
<b>xxxxx</b>	Number of rewrite (5 characters)
<b>yyyyy</b>	Progressive weighing (6 characters)
<b>Example</b>	PIDST,1, 1500,0kg,PT 2,8kg,00000-000158<CR><LF>

### Reading a stored weighing


<b>Command</b>	<b>nnALRDxxxxx-yyyyy&lt;CR&gt;&lt;LF&gt;</b>
	Where xxxx is the rewrite number, yyyy is the weighing sequence.
<b>Response</b>	<b>s , w w w w w w w w w u u , p p t t t t t t t t u u&lt;CR&gt;&lt;LF&gt;</b>
where:	
<b>s</b>	Number of scales (always 1)
<b>w...w</b>	Gross weight (10 characters)
<b>uu</b>	Unit of measurement (“g”, “kg”, “t”, “lb”)
<b>pp</b>	Type of tare: double space “ “ if semi-automatic, “PT” if preset (2 characters)
<b>t...t</b>	Tare value (10 characters)
<b>Example</b>	ALRD00000-000158<CR><LF> 1, 1500,0kg, 2,8kg<CR><LF>

## 8. WIRING DIAGRAMS

CPU board (DFWL-1x, DFWLI-1x, TPWNBT-1x)




RS232 serial port with RJ11 connector




PIN	MEANING
2	TX
4	GND
5	RX

Optional IN/OUT DFIO board



## Optional analogue DAC16OSER output board



OPERATION RANGE (only for live analogue output)

0 / 10 V

-10 / 10 V

0 / 5 V

-5 / 5 V

## 9. PROGRAMMING ERRORS

MESSAGE	DESCRIPTION	SOLUTION
<i>AL.Err</i>	“Alibi memory” board (optional) not detected.	Check the presence of the board inside the indicator. If present, check it is not damaged and is installed correctly.
<i>Er.I.b.H</i>	“inputs / outputs” board (optional) not detected.	Check the presence of the board inside the indicator. If missing, deactivate any inputs or outputs (parameter “ <i>inPut5</i> ” or “ <i>outPut</i> ”, see page 37-38). If present, check it is not damaged and is installed correctly.
<i>Er.r.b.H</i>		
<i>Eq.Err</i>	Impossible to perform equalisation.	Check the cells are connected properly. Check the signal of each cell in the diagnostic menu (menu <i>d.iRG</i> , parameter <i>RdC.uU</i> , see page 39).
<i>PrEC.</i>	Calibration error.	First calibrate the zero point, then proceed with the next points.
<i>Err.Pnt</i>	Calibration error.	Check the connection of the load cell. Check that the cell signal is stable, valid and greater than that of the previously acquired point.
<i>Er.11</i>	Calibration error.	Increase the calibration weight.
<i>Er.12</i>	Calibration error.	Check that the signal coming from the cell increases upon the increasing of the weight loaded on the scale. When acquiring the calibration points, use the increasing calibration weights.
<i>Er.37</i>	Calibration error.	Repeat the calibration, checking that the capacity and division have been correctly set.
<i>Er.39</i>	Instrument not configured.	Reset the factory configurations (menu <i>AdUAnC</i> , parameter <i>dFLt.t</i> , see page 46).
<i>Er.85</i>	Instrument configured but not calibrated.	Perform calibration.
<i>C.Er.36</i>	Calibration error.	Check that the signal coming from the load cell is not negative.
<i>Err.Not</i>	Unstable weight	Check in the menu <i>d.iRG</i> , parameter <i>RdC.uU</i> (see page 39) that the signal is stable and try again. If the connection of the cells is with 4 wires, check that the sense jumpers are inserted.

## 10. SUMMARY OF THE PARAMETERS

<b>CAL</b>	Calibration	11
<b>dIV</b>	Division	11
<b>0.CAL</b>	Zeroing the pre-tare (zero calibration)	12
<b>GrAU</b>	Area of gravity of the place of use	12
<b>SERIAL</b>	Configuration of the serial ports	13
<b>CoAPC</b>	PC port configuration (communication with PC, PLC or repeater)	13
<b>Node</b>	Selection of the communication mode	13
<b>Protocol</b>	Communication protocol	13
<b>CoSEL</b>	COM port selection for use as PC port	14
<b>bArd</b>	Communication speed (baud rate)	14
<b>bIt</b>	Configuration of the serial protocol	14
<b>CoPrn</b>	PRN port configuration (communication with printer or repeater)	15
<b>Node</b>	Selection of the communication mode	15
<b>Protocol</b>	Communication protocol	15
<b>bArd</b>	Communication speed (baud rate)	15
<b>bIt</b>	Configuration of the serial protocol	16
<b>Cts</b>	Printer control signal	16
<b>PoErP</b>	Printer power supply	16
<b>RuH.1</b>	Communication with PC, PLC or repeater	17
<b>Node</b>	Selection of the communication mode	17
<b>Protocol</b>	Communication protocol	17
<b>bArd</b>	Communication speed (baud rate)	17
<b>bIt</b>	Configuration of the serial protocol	18
<b>RuH.2</b>	Communication with PC, PLC or repeater	17
<b>Node</b>	Selection of the communication mode	17
<b>Protocol</b>	Communication protocol	17
<b>bArd</b>	Communication speed (baud rate)	17
<b>bIt</b>	Configuration of the serial protocol	18
<b>uSb</b>	Communication with PC, PLC or repeater	18
<b>AdUAnC</b>	Advanced configurations	19
<b>rAd io</b>	Connection port of radio-frequency module	19
<b>tTLE il</b>	TTL port / Inclinometer activation	19
<b>tErn</b>	Closing character of each print line	19
<b>iGnorE</b>	Ignore unknown commands	19
<b>LAYout</b>	Print customisation	20
<b>LAng</b>	Print language settings	21
<b>ChAr</b>	Setting the font	21
<b>hEAdEr</b>	Print header	22
<b>dAtA</b>	Selection of the weight data	24
<b>HE ght</b>	Progressive weighed	24
<b>tICET</b>	Ticket/label progressive	24
<b>CLoCH</b>	Date and time	25
<b>bArC.39</b>	Bar code 39	25
<b>bArC.uP</b>	Barcode top margin (mm)	25
<b>bArC.L</b>	Barcode left margin (mm)	25
<b>bArC.h</b>	Barcode height (mm)	25
<b>bArC.dt</b>	Selection of the weight data	26
<b>CoPIES</b>	Multi-copy prints	26

<b>Endt<i>IC</i></b>	Paper outlet for end of ticket/receipt	26
<b>bl<i>inE</i></b>	White print head preheating line (thermal printer only)	26
<b>LA<b>E</b>l</b>	Label configuration	27
<b>Lb<i>SaUE</i></b>	Saving labels in printer memory	27
<b>tESt</b>	Test print all formats	27
<b>F<i>ilteR</i></b>	Weighing filters	30
<b>Sc<i>rEEn</i></b>	Adjusting the display	29
<b>bA<b>R</b>l<i>iE</i></b>	Backlighting	29
<b>br<i>uHt</i></b>	Brightness	29
<b>La<i>Ch</i></b>	Display lock (for use by the manufacturer)	29
<b>Co<i>lour</i></b>	Backlight colour	29
<b>bAt<i>t</i></b>	Battery power supply	30
<b>Ec<i>oBaT</i></b>	Energy saving for battery operation	30
<b>Au<i>toFF</i></b>	Auto switch-off	31
<b>rE<i>nOte</i></b>	Remote control	31
<b>An<i>out</i></b>	Analogue output	32
<b>in<i>PutS</i></b>	Digital inputs	34
<b>ou<i>tPut</i></b>	Digital outputs	35
<b>rE<i>SEt</i></b>	Factory configuration reset	36
<b>d<i>iaG</i></b>	Diagnostics	36
<b>Ad<i>C.uU</i></b>	Converter ( $\mu$ V)	36
<b>d<i>SP</i>LA</b>	Display	36
<b>KEy<i>b</i></b>	Keypad	36
<b>C<i>tS</i></b>	CTS status	36
<b>ou<i>tPut</i></b>	Digital outputs	36
<b>in<i>PutS</i></b>	Digital inputs	36
<b>An<i>out</i></b>	Analogue output	36
<b>SE<i>rnufl</i></b>	Serial number	36
<b>Pr<i>GUEr</i></b>	Firmware release	36
<b>d<i>uL.int</i></b>	Internal divisions	36
<b>Ad<i>C.Pnt</i></b>	Converter (ADC points)	36
<b>bt<i>AdC</i></b>	Battery voltage	36
<b>Ph<i>AdC</i></b>	Mains power supply voltage	36
<b>SE<i>rl</i>AL</b>	Bridge between serial ports	36
<b>Ad<i>UAnC</i></b>	Advanced	37
<b>CAL<i>Par</i></b>	Calibration parameters	37
<b>dEC<i>.nT</i></b>	Configuration of the decimal point	37
<b>d<i>u</i></b>	Reading division	37
<b>u<i>U.</i></b>	Unit of measure	37
<b>rAn<i>GE</i> 1</b>	Scale capacity (maximum capacity / first weighing range)	38
<b>rAn<i>GE</i> 2</b>	For multirange scales (second weighing range)	38
<b>rAn<i>GE</i> 3</b>	For multirange scales (third weighing range)	38
<b>Eq<i>uAL</i></b>	Equalisation function	38
<b>n<i>ChAn</i></b>	Equalised analogue channels	38
<b>Eq<i>uALP</i></b>	Equalisation	39
<b>CAL<i>AdU</i></b>	Complete calibration	42
<b>St<i>abFle</i></b>	Additional stability filter	40
<b>PE<i>arFL</i></b>	Anti-peak filter	41

<b>M</b> etrological parameters	41	
<b>O</b> PERC	Reset percentage via key (▼)	41
<b>d</b> WSTB	Sensitivity of the weight stability control	41
<b>t</b> WSTB	Stability detection time	41
<b>Z</b> HFT	Zero hold function (tracking)	41
<b>Z</b> TRSP	Zero tracking speed	41
<b>on.2Ero</b>	Reset at power and reset percentage	42
<b>CALAdd</b>	Re-acquisition / change of the calibration points in memory	42
<b>CALMan</b>	Manual calibration (via insertion of ADC points)	42
<b>dSALE</b>	Limitations for direct sales	42
<b>K</b> EYb	Type of keypad	42
<b>I</b> L <small>t</small>	Inclinometer (for use by the manufacturer)	42
<b>r</b> EACT	Reactivation of the print or weight totalisation function	43
<b>LoCFb</b>	Permanent keypad lock (excluding key (C))	43
<b>R</b> ELibir	Reset of fiscal memory (alibi memory, optional)	43
<b>P</b> in. <b>E</b> EC	Access PIN to programming menu	43
<b>P</b> in. <b>u</b> SE	Access PIN to user menus	43
<b>d</b> FLET	Total reset of memory and calibration	43

# 11. FAQ - Frequently Asked Questions

## Calibration

---

### Can I change the maximum capacity without recalibrating?

Yes, you must change the parameters [rAnGE 1.2.3](#) (Q-1-4,5,6). (See page 41)

### Can I change the division without recalibrating?

Yes, you must change the parameter [d.iU](#) (Q-1-2). (See page 40)

### Can I change the position of the decimal point without recalibrating?

Yes, you must change the parameter [dEC.iT](#) (Q-1-1) and the value of the calibration points using step [CAL.PAn](#) (Q-5-6). (See page 40 and 45)

### Can I calibrate the instrument in “multi-division” mode?

Yes, using the advanced configuration function from PC and the Dinitools program.

## Communication

---

### Scale doesn't answer

- Check that the cable is in good condition and that there are no faults (use a multimeter).
- Check that the communication port of the PC or device being used is not compromised. If necessary, try another device / PC.
- Check that you have connected the cable to the correct serial port.
- Check step configuration [bAud](#) and [b.iT5](#). (See page 17)
- Temporarily activate continuous communication and retry string reception. If the string has been received correctly, carefully check the syntax of the command sent, the communication timeouts and the presence of the terminator.

## Generic

---

### The scale does not turn on

- Check that the input voltage level to the motherboard is correct.
- Try the forced power by inserting the “ON BOOT” jumper present on the motherboard. If the indicator lights up, check the correct operation of the keypad, using the diagnostics menu [d.RG](#). (See page 39)
- Possible failure of the internal rechargeable battery (if present).

## Notes

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

This publication, or portions thereof, may not be duplicated without written permission from the Manufacturer. All information in this manual is based on the data available at the time of its publication; the Manufacturer reserves the right to make changes to its products at any time, without notice and without incurring any penalty. We therefore recommend that you always check for updates.

The person responsible for the use of the scale must ensure that all safety regulations in force in the country of use are applied, ensure that the scale is employed in accordance with the intended use and avoid any dangerous situation for the user.

The Manufacturer declines all responsibility for any weighing errors.





A RICE LAKE WEIGHING SYSTEMS COMPANY

#### **HEAD OFFICE**

Via Della Fisica, 20  
41042 Spezzano di Fiorano, Modena - Italy  
Tel. +39 0536 843418 - Fax +39 0536 843521

#### **SERVICE ASSISTANCE**

Via Dell'Elettronica, 15  
41042 Spezzano di Fiorano, Modena - Italy  
Tel. +39 0536 921784 - Fax +39 0536 926654

[www.diniargeo.com](http://www.diniargeo.com)

Stamp of the authorised service centre