

USER GUIDE TPWET01

PALLET TRUCK SCALES TPWET01



Page intentionally left blank.

Table of contents

1	INTRODU	ICTION	5
0	PERATING IN	ISTRUCTION	7
	1.1.1	Weighing	7
	1.1.2	Controls	8
	1.1.3	Maintenance Warnings	8
	1.1.4	Rudder assembly	8
	1.1.5	Descending speed regulation	8
	1.1.6	Oil level	9
	1.2 DAII	Y MAINTENANCE	9
	1.3 SCH	EDULED MAINTENANCE	9
	1.4 REFI	ERENCE DRAWINGS	10
2	TECHNIC	AL SPECIFICATIONS	12
	2.2 POV	VER SUPPLY AND START UP	13
	Start up		13
	Turning off	the instrument	14
2	INDICATO	DR PARTS	15
	Display		16
	Display Ir	ndicators	18
	Numeric	input	19
	Alphanur	meric input	19
	Keyboard		19
	Cross light.		20
3	MAIN FU	NCTIONING DESCRIPTION	21
	Zeroing		21
	Tare		22
	Semiauto	omatic tare	22
	Preset ta	re	22
	Link a pre	eset tare to an article	23
	Tare cand	cellation	23
	Locked/u	ınlocked tare	23
	Input texts.		24
	Databases .		25
	Insertion		25

TPWET01 USER GUIDE

	Modification	26
	Cancellation	27
	Selection	28
	Deselection	29
	Insertion and quick selection of the temporary element	30
	Alphanumeric search	31
	Search by element index	31
	Printouts	32
:	Setpoints	33
WI	EIGHING PROCEDURE	35
	Totalisation in loading	35
•	Totalisation in unloading	36
•	Totalisation in loading as well in unloading	36
•	Totalisation with automatic execution of the tare	36
	Manual or automatic totalisation	36
•	Totalisation delay	37
	Totalisation field	37
	Error messages	37
	Conditions for totalisation	37
	Progressives	38
	Additional value	38
	Progressive digits	38
	Ticket progressive	38
	Lot progressive	38

1 INTRODUCTION

This manual was created to help you install and learn all about the functional possibilities of the purchased indicator.

The instrument is suitable for use in various weighing environments.

Not only does it have all the normal features of high-precision scales, but it also gives you the possibility to work in specific environments due to the functioning modes contained in the software implemented in the FLASH MEMORY on the internal board. This makes the instrument extremely flexible and it can be used in many different industrial applications linked to weighing. The touch screen, the numerical and function keyboard, allow the operator an easy and immediate use and provide the microcontroller with DATA ENTRY functions in addition to the normal weighing functions. The input/output allows the instrument to control various external devices, to receive external commands, control a printer and communicate with a personal computer or to be inserted in a network of weight indicators controlled by a PC.



WARNING

Please note that this instrument is covered by a warranty and **MUST NOT BE OPENED BY THE USER** for any reason whatsoever. Any attempt to repair or modify the unit exposes the user to the risk of electric shock and will invalidate the entire warranty.

If any problems are found in the unit or with the system in which it is used, the fact must be communicated to the manufacturer or the dealer from whom it was purchased.

In any case, **DISCONNECT THE POWER SUPPLY** before taking any action.

- Do not pour liquids on the weight indicator.
- Do not use solvents to clean the weight indicator.
- Do not expose the instrument to direct sunlight nor place it near heat sources.
- Place or anchor the weight indicator and platform on a non-vibrating base.
- ♣ All the connections of the indicator have to be made respecting the rules applicable in the zone and in the installing environment.

Everything not expressly described in this manual has to be considered as improper use of the equipment.

Do not install in any area where there is a risk of explosion.



The crossed-out wheeled bin on the product means that at the product end of life, it must be taken to separate collection or to the reseller when a new equivalent type of equipment is purchased. The adequate differentiated refuse collection in having the product recycled, helps to avoid possible negative effects on the environment and health and supports the

recycling of the materials of which the equipment is made. The unlawful disposal of the product by the user will entail fines foreseen by the current regulations.

Used symbols through the manual

\triangle	ATTENTION! Only qualified personnel must perform this operation					
\wedge	ATTENTION! This is referred to working with live wires: only qualified personnel must perform					
4	this operation.					
CE	CE CONFORMITY					
(III)	IDENTIFIES THE CLASS OF PRECISION.					
	It identifies an advanced function explained in the technical manual (for technical					
	personnel).					

This pallet truck scale has been designed to only weigh on pallets.

Never exceed maximum load, see the weight indicator's label.

Do not use in an environment with any risk of explosion.

Load only when forks are in the lowest position.

Check that the pallet truck scale is in good operating conditions.

To get the best weighing results, lift up the forks about 5-10 cm.


Do not expose the weighting indicator to atmospheric agents (rain, sun, etc.).

All the connections of the indicator have to be made respecting the rules applicable in the zone and in the installing environment.

Read and understand all instructions.

In case of approved scale, the weighing has to be done on a EUR-EPAL 800x1200mm pallet (ref. Norms UIC 435-2 and UIC 435-4).

FIX THE LOAD ON THE PALLET, AS SHOWN IN THE DRAWING.



THE PARTS OF THE INSTRUMENT CONTAINING DANGEROUS ELECTRICAL TENSION ARE ISOLATED AND INACCESSIBLE TO THE USER UNLESS IT HAS BEEN DAMAGED, OPENED, OR ALTERED.

OPERATING INSTRUCTION

A pallet truck scale is an electronic weighing system directly installed on a pallet truck; it must be used on even solid surfaces and driven always in the normal position. Before loading, check the maximum load allowed by the pallet truck scale in use (refer to instruction plate on the side of the pallet truck). The rudder has a double function, direction control and hydraulic lifting.

N.B. Lift up or pull down only when the pallet truck scale is in a standing still position.

1.1.1 Weighing

In order to obtain correct weighing results, one is required to use the pallet truck scale on a flat surface, lift up the forks about 5-10 cm (see the following "CONTROLS" chapter) and wait for the stability before the weight reading.

1.1.2 Controls

The lever on the right side of the rudder can be put in 3 positions, like it shows on the plate "Y" in figure B.

POS. 1 – centre = **TRANSPORT** The rudder is completely free to allow driving control.

POS. 2 – down = **LIFT UP** By moving the lever downward the lifting mechanism is activated.

Pushing down the rudder will cause the load to lift up.

POS. 3 – up = **PULL DOWN** By moving the lever upward the load will descend. When the lever is

quickly moved upward, a special valve controls the descending speed of the load.

1.1.3 Maintenance Warnings

Before you perform any service, make sure the pallet truck is in a condition of safety.

Never discharge any residue without taking the necessary environmental precautions.

Only perform the service described in this manual. Maintenance and repair jobs not included in this manual must be performed by authorised personnel only.

Serious injury could result from service or maintenance performed by unqualified personnel.

- Never alter the safety level of the machine. Always use identical replacement parts.
- Never remove or hide in anyway instruction plates and stickers.
- Do not modify the pallet truck.
- Do not use inflammable cleaners. Do not use direct jets of water. Do not pour liquids on the indicator.

1.1.4 Rudder assembly

- 1. Lock rudder (228) to hydraulic pump (200) with screws (27) that you can find in the box.
- 2. Lock chain (208) to lift down pedal (50). Rotate pedal to simplify the connection.

1.1.5 Descending speed regulation

- 1. Lift up forks to maximum height.
- 2. Set right lever to POS. 1 (centre).
- 3. Make sure the rudder (200) is in a vertical position.
- 4. Unscrew bolt (2) and turn clockwise the adjustable screw (48) until the forks start to descend.
- 5. Turn adjustable screw 1 ½ turn counter clockwise, then screw bolt (2).
- You should be able to obtain a descending movement from every position of the rudder.

1.1.6 Oil level

Check oil level every 6 months. Only use hydraulic oil. No engine oil or brake oil.

Oil viscosity 30 Cst at 40°C. Quantity 0.3 lt.

With the fork in the lower position follow these steps:

- 1. Remove cover (204), o-ring (11) and cap (202).
- 2. If necessary add oil. Maximum filling level is 200mm below top of tank.
- 3. Turn on the pump to get air out of the hydraulic circuit.
- 4. Put cap (202), o-ring (11) and cover (204) back.

1.2 DAILY MAINTENANCE

To keep the pallet truck scale in good operating condition, the operator must perform daily these checkpoints:

- Check overall conditions.
- Check weighing scale.
- Check printer (if installed).
- Check pump.
- Check rollers and wheels.

1.3 SCHEDULED MAINTENANCE


Maintenance performed by qualified personnel only. Make sure to put the pallet truck scale on a flat and solid surface.


- Check that nothing is blocking the rollers.
- Grease rollers and wheels bearings.
- Grease control lever on rudder.
- Check oil every six months. Fill up if necessary with IP46 hydraulic oil.

N.B. If oil needs to be replaced, follow the necessary precaution and law requirements for the disposal of the exhausted oil.

Replace rollers and wheels when necessary.For any questions or problems check with an Authorised service Centre.

1.4 REFERENCE DRAWINGS





LUBRIFICATION POINTS

Ref. "K" fig. D needs silicon oil for food industry, expiry of 1 month.

Ref. "P" fig. D needs silicon grease for food industry, expiry of 2 months.

TECHNICAL SPECIFICATIONS

	40.7/1 / 0 - 24.7/1 : 1/ 10						
POWER SUPPLY	12 Vdc (8 ÷ 24 Vdc in the IO versions), with internal 100 ÷ 240 Vac (50÷60 Hz) / 12 Vdc adapter.						
MAXIMUM POWER	16 VA.						
OPERATING TEMPERATURE	From -10 to +40 °C.						
CONVERTER	24 bit Sigma Delta.						
CONVERSION SPEED	200 conv./sec with automatic selection.						
RANGE OF INPUT SIGNAL	0.6 mV/V – 3.2 mV/V.						
MINIMUM VOLTAGE PER DIVISION	0.3 μV (approved instrument); 0.03 μV (non-approved instrument).						
AUTOMATIC ZERO DETECTION	Only in gross mode, programmable at +/- ¼, ½, 1, 2 divisions.						
ZERO RANGE	Configurable up to +/- 50% of max load capacity.						
AUTO ZERO AT START-UP	Configurable up to +/- 50% of max load capacity.						
LOAD CELL POWER SUPPLY	5Vdc ± 5%, 120mA (max 8 350Ω cells).						
LOAD CELL CONNECTIONS	6 wires with Remote Sense.						
DISPLAY DIVISIONS	10000e, 3 x 3000e for legal for trade weighing, expandable up to 800.000 for internal use (with minimum signal coming from the 1.6 mV/V cell).						
DISPLAYS	Graphic touch screen 320x240 dots (black & white).						
DATABASE/MEMORY	Articles database of 1000 items (3 descriptions of 25 characters each, linked tare, linked customer, 3 setpoints) Customers database of 200 items (5 descriptions of 30 characters each) Tare database (300 items for every scale)						
SIGNALS	3-way control light						
KEYBOARD	Impermeable polycarbonate keyboard (IP65 protection degree), with membrane keys with audible and tactile feedback.						
PARAMETER SETUP	Calibration and linearity (up to 8 points), fully digital and programmable from the keyboard or from PC with Dinitools ™.						
CLOCK/DATE	Fitted, with buffer RAM.						
SERIAL OUTPUTS	 - 2 input/output RS232 ports on terminal board/ amp connector. - 1 input/output RS485 port on terminal board or RS232 on amp connector. 						
INPUTS AND OUTPUTS	 - Management of PC keyboard or barcode reader - 2 optoisolated inputs (optoisolated photo couplers), 12Vdc – 24Vdc, 20mA max - 4 outputs (optoisolated photomosfets), 48Vac / 0.15A, 60Vdc / 0.15A, 10Ω max. With IO expansion: - 8 inputs (optoisolated photo couplers), 12Vdc – 24Vdc, 20mA max. - 16 outputs (optoisolated photomosfets), 48Vac / 0.15A, 60Vdc / 0.15A, 10Ω max. 						
ANALOG OUTPUT (with analog expansion board)	- 16-bit analogue output configurable from keyboard (full-scale value; zero scale value and minimum value) from 0 to 10 Vdc or from 0 to 20mA; the maximum resistance applicable on the output current is 350 Ω and the minimum resistance applicable on the output voltage is 10 $k\Omega$.						

2.1 POWER SUPPLY AND START UP

The instruments are powered with a 6Vdc rechargeable internal battery.

It is possible to charge the battery through the 12V power adapter which should be connected to the 230 Vac mains voltage.

Safety norms must be respected for the connection to the mains voltage <u>including the use of a line which</u> has to be free from noise generated by other electronic equipment.

BATTERY CHARACTERISTICS

Material: LEAD

Power: 4,5 Ah or 10 Ah

Output: 6 V


THE BATTERY MUST ONLY BE REPLACED WITH AN ORIGINAL FROM THE MANUFACTURER.

In order **TO CHARGE THE BATTERY** through the 230Vac mains, one should insert the plug end of the AC/DC power adapter into the socket on the column, and the power adapter to your 230Vac current source.

2.2 Start up

Step	Description	Screen				
1	Press the key until the instrument powers on	10000000000000000000000000000000000000				
2	The logo (Logo to show at the start up) and the software version appear for some instants. EGT-AF01-XX is the name of the installed software, in which XX identifies the language. XX.YY is the installed software version.	Scales - Weighing systems : www.diniargeo.com : info@diniargeo.com : +39 0536 843418				

TECHNICAL SPECIFICATIONS



2.3 Turning off the instrument

To turn off the indicator press the key until the logo appears on the display.

3 INDICATOR PARTS




Figure 1. Front panel

Part	Description
1	Touch screen
2	Cross light (3 colors)
3	Keyboard

3.1 Display

The indicator presents 2 main screens, illustrated in the below scheme:




Figure 2. First main screen




Figure 3. Second main screen


INDICATOR PARTS

Element	Description							
1	Display indicators							
2	Active scale							
	Touch to switch to the next scale							
3	Time and date							
	Touch to change the date							
4	Weight value on the active scale							
	Touch to tare the gross weight							
5	Tare value							
	Touch to insert a preset tare							
6	Description of the first input text (LOT)							
	Touch to change the description of the first input text							
7	Net value of the partial total							
	Touch to print and reset the partial total							
8	Number of weighs of the partial total							
	Touch to print and reset the partial total							
9	Net value of the general total							
	Touch to print and reset the general total							
10	Number of weighs of the general total							
	Touch to print and reset the general total							
11	Selected article							
	Touch to select an article							
12	Selected customer							
	Touch to select a customer							
13	System messages area							
14	Touch to zero the scale							
15	Touch to total							
16	Touch to print							
17	Touch to switch to the next screen							
18	Touch to manage the articles database							
19	Touch to manage the customers database							
20	Touch to access to the indicator functions							
21	Touch to manage the input texts							
22	Touch to manage the setpoints							

3.1.1 Display Indicators

Symbol	Description
ΔΩ ₄	The weight detected by the weighing system is near the zero,
701	included within the interval of $-1/4$ and $+1/4$ of the scale
	division
~	The weight is unstable
+T+	A tare value has been acquired
PT	A preset tare value has been entered
W1W2W3	Active weighing range
9	Locked keyboard
-aa	Transmission of the data to the printer serial port underway

3.1.2 Numeric input



3.1.3 Alphanumeric input

Screen										Function
Line 0									=	Allows to insert an alphanumeric text.
Esc		,	<	7	1	Clear		BkSp		← →: scroll left or right Clear: clears all the text
	2	3	4	5	6	7	8	9	0	Bksp: backspace
q	v	e	r	t	y	u	i	0	p	2^F : switches to special characters
ä	5	d	1	9	h	3	k	1	-	Shift : changes the character case and switch
Pp.	2	×	¢	v	b	n	n			between letter and number modes
Shift ← → OK		IK	OK: exit saving the text							
										Esc: exit without saving the text
										NOTE: on the first pressed key all the field i replaced

3.2 Keyboard

Key	Function					
(b)	Press to clear the tare					
CLEAR	Press for a long time to power on/off the instrument					
TARE	Press to tare the gross weight					
A'A HELP	Press to switch to the next scale					
ZERO	Press to zero the scale					
≫	Press to switch to the next screen					
	Press to insert the preset tare					

3.3 Cross light

The standard functioning in the weighing environment is described in the table:


Step	Description	Light
1	The net weight is below setpoint 1 or is unstable (cross light turned off)	
		crosslight
2	The net weight is greater or equal setpoint 1 (see section 0) and is	7
	stable (yellow light turned on)	crosslight
3	The net weight is greater or equal setpoint 2 (see section 0) and is stable (green light turned on)	
		crosslight
4	The net weight is greater or equal setpoint 3 (see section 0) and is stable (red light turned on)	crosslight

4 MAIN FUNCTIONING DESCRIPTION

All the functions of the indicator are available from the functions are divided into the following groups:


Group	Description
Scale functions	Operations to the weight (zeroing, tare,)
Printout	Print functions management
Generic functions	Generic operations to the indicator (lock keyboard,
	calculator,)
Diagnostic	Functions to check the peripheral units working state
Input texts	Input texts management
Databases	Databases management
AF01 functions	Total operations
Totals	Print and reset of the totals
Progressives	Weigh progressives management

4.1 Zeroing




4.2 Tare

4.2.1 Semiautomatic tare



4.2.2 Preset tare

Description	Screen
Touch on the tare area	U1 2.000 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1



4.2.3 Link a preset tare to an article

It's possible to insert the tare value of an article in the database. By selecting the article the preset tare is activated.

4.2.4 Tare cancellation


It's possible to cancel the stored tare value in the following ways:

- By touching the weight area or by pressing the when the platform is unloaded
- By setting the preset tare value to 0
- By pressing the key

4.2.5 Locked/unlocked tare


Normally the tare is active until the cancellation operation (locked tare). One can also choose that the tare value is cancelled automatically when the scale is unloaded (unlocked tare) through Menu \rightarrow Scale functions \rightarrow Lock/Unlock tare function.

4.3 Input texts




4.4 Databases


4.4.1 Insertion



4.4.2 Modification



4.4.3 Cancellation



4.4.4 Selection

Step	Description	Screen
1	Touch the button in the first main screen to get access to the elements present into desired database	0.500 1.500
2	Touch the desired element to select	Selected Article Selected Article: NO Esc DESELECT PaZ PINDEX
3	The description of selected element appears on the display	U1

4.4.5 Deselection

Step	Description	Screen
1	Touch the button in the first main screen to get access to the elements present into desired database	PT W1
2	A message indicates the index of the selected element. Touch the DESELECT button to deselect this element	Select Article 0000 TOMATO Selected Article: 0000 Esc. DESELECT Pa2 PINDEX
3	Press the button to confirm or not the deselection	Deselect the record? No Yes Lot DESCRICT Pa. 2 PINNER
4	The description of previous selected element disappears on the display	PT U1

4.4.6 Insertion and quick selection of the temporary element

Step	Description	Screen
2	Touch the button in the first main screen to get access to the elements present into desired database Touch the element 0000 to insert the	1.500 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
2	temporary element: the previous element will be cleared	Selected Article: 0001 Esc DESELECT PAZ PINDEX
3	Touch the first field to insert the content	Description 1 Description 2 Description 3 Linked tare Empty Linked customer Setpoint 1 Setpoint 2 Setpoint 3 O.000kg
4	Insert the content of the field and confirm it with the OK button	POT Esc - > 7) Clear BkSp † R B S % ^ 8 - () Q U E R T Y U I O P A S D F G H J K L : #** Z X E U B H H < > Shift + + OK
5	Repeat the operation for the desired fields and press the button to confirm and select it immediately or the DELETE button to cancel	POTATO Description 1 POTATO Description 2 Description 3 Linked tare Empty Linked customer Empty Setpoint 1 0.000kg Setpoint 2 0.000kg Setpoint 3 0.000kg
6	The description of element 0000 appears on the display	U1

4.4.7 Alphanumeric search

Step	Description	Screen
1	Touch the AZ button in the database update/selection screen	RETICLE
2	Insert the first characters of the element to search	### ##################################
3	The table shows all the elements starting with the typed characters. Then touch the desired element	### ##################################

4.4.8 Search by element index

Step	Description	Screen
1	Touch the INDEX button in the database update/selection screen	SCINCT AFTICION OOOD TOMATO OOOT SALAB OOOZ POTATO OOOS PUMPKIM OOOF FLOUR OOOS CORN OOOF PEACH OOO7 GRAPE Selected Article: OOOZ ESC DESELECT PA.Z PINDEX
2	Insert the index of the desired element and confirm. In selection the element is selected and the main screen is displayed. In update the element fields are displayed and can be modified.	O

4.5 Printouts

The indicator has 22 print functions, each function has an associated format. When a function has been put into execution through the operation illustrated in the scheme, the associated format is sent to the print serial port.

There are 30 available formats to associate to the print functions. To change the format of the print function use MENU \rightarrow Printout \rightarrow Change the printout format.

Nr.	Print function	Operation / Notes	Format
1	SIMPLE PRINTOUT	PRINT in the main screen toolbar.	1
		With the approved instrument the net weight must be	
		greater or equal to 20 divisions.	
		With the non approved instrument the net weight must be	
		greater than zero.	
2	TOTALISATION	in the main screen toolbar	2
3	PARTIAL TOTAL	MENU → Totals → Print partial total	3
4	GENERAL TOTAL	MENU → Totals → Print general total	4
5	GRAND TOTAL	MENU → Totals → Print grand total	5
6	HEADING OF FIRST	in the main screen toolbar	6
	TOTALISATION	Printed when general totals weighs changes to 1	
7	HANDLED ARTICLE TOTAL	MENU → Totals → Print article total	7
		MENU → Totals → Print articles total	
	LIST OF WEIGHS	MENU → AF01 functions → Print article list	
	CONDITIONED BY THE	Formats 8, 9, 10, 11 are related to article weighs list	
	ARTICLE		
8	LIST HEADING	Printed before the 1st list item	8
9	SINGLE WEIGH	Single item print format	9
10	SECTOR END	Printed after the set number of items (see print block "Print	10
		lines for the weigh list")	
11	LIST END	Printed after the last item	11
	LIST OF WEIGHS	MENU → AF01 functions → Print customer list	
	CONDITIONED BY THE CUSTOMER	Formats 12,13, 14, 15 are related to customer weighs list	
12	LIST HEADING	Printed before the 1st list item	12
13	SINGLE WEIGH	Single item print format	13
14	SECTOR END	Printed after the set number of items (see print block "Print	14
		lines for the weigh list")	
15	LIST END	Printed after the last item	15
	LIST OF ALL THE WEIGHS	MENU → Af01 functions → Print weighs list	
		Formats 16,17, 18, 19 are related to all weighs list	
16	LIST HEADING	Printed before the 1st list item	16
17	SINGLE WEIGH	Single item print format	17 18
18	SECTOR END	Printed after the set number of items (see print block "Print	
		lines for the weigh list")	
19	LIST END	Printed after the last item	19
20	RESULT OF THE	MENU → Generic functions → Calculator	20
	CALCULATOR		

21	HANDLED CUSTOMER	MENU → Totals → Print customer total	21
	TOTAL	MENU → Totals → Print customers total	
22	PRINT AT START-UP	Printed at start-up after the auto-zeroing procedure	22

4.6 Setpoints

To set the setpoints thresholds follow the path MENU \rightarrow Generic functions \rightarrow **Outputs setpoint setting**. A screen like the of Figure 4 is displayed. In the example outputs 1, 2 and 3 are configured with hysteresys disabled (Digital outputs).

Press one of the three ON values, the usual numeric input screen is displayed. Insert the desired value. At the end press **Esc** to go back to Generic functions menu.




Figure 4. Setpoints thresholds setting

5 WEIGHING PROCEDURE

The programme has been made to manage the accumulation and the printing of the weight and quantity. The totalisation takes place in the ways selectable in the technical set-up, described in the following section. The totalised weight and quantity are automatically accumulated in the instrument totals (PARTIAL, GENERAL, GRAND TOTAL), and the weighs' progressives are automatically increased relative to the previously shown totals.

Furthermore, if an article has been enabled, the instrument increases both the totals as well as the weighs' progressive relative to the selected article.

The data that is increased is:

- WEIGH NUMBER
- GROSS WEIGHT TOTAL
- NET WEIGHT TOTAL
- TARE TOTAL

The indicator allows to accumulate the weight on the scale in different modes:

- Totalisation in loading.
- Totalisation in unloading.
- Totalisation both in loading as well as in unloading.



5.1 Totalisation in loading

In loading mode positive net weights only are totalised.

To totalise follow the steps below:

- 1. Put the article on the scale and wait for the weight to become stable
- 2. Touch the toolbar ______ button
- 3. If the weight is not stable the screen of Figure 5 is displayed
- 4. On totalisation failure the system message "NOT VALID OR UNSTABLE WEIGHT" appears, as in Figure 6
- 5. On success the totals are incremented (Figure 7) and the printout, if configured, is executed
- 6. Remove the article from the scale and repeat from step 1 with another article




Figure 5. Totalisation underway (loading mode)




Figure 6. Totalisation failure (loading mode)





Figure 7. Totalisation success (loading mode)

5.2 Totalisation in unloading

In unloading mode negative net weights only are totalised.

To totalise follow the steps below:

- 1. Put the article on the scale and wait for the weight to become stable
- 2. Tare the scale by touching the weight area or pressing the tare key
- 3. Touch the toolbar TOTAL button
- 4. If the weight is not stable the screen of Figure 8 is displayed
- 5. On totalisation failure the system message "NOT VALID OR UNSTABLE WEIGHT" appears, as in Figure 9
- 6. On success the totals are incremented (Figure 10) and the printout, if configured, is executed
- 7. Remove the article from the scale and repeat from step 1 with another article








Figure 9. Totalisation failure (unloading mode)




Figure 10. Totalisation success (unloading mode)

5.3 Totalisation in loading as well in unloading

This type of totaliser allows to totalise both positive net weights as well as negative net weights. Follow the steps of section 5.1 for loading totalisation, the steps of section 5.2 for unloading totalisation.

5.4 Totalisation with automatic execution of the tare

This function is useful for formulation or dosage applications and allows to automatically tare after the accumulation of the weight on the scale (both in loading as well as in unloading, and manually as well as automatically), allowing to totalise the subsequent one on its own and without unloading the scale.

Tare after the totalisation.

5.5 Manual or automatic totalisation

The operation of accumulation, normally done manually with ton, can be done automatically when the weight is stable.

Totalisation mode.

5.6 Totalisation delay

Only with the automatic totalisation is it possible to set a delay for acquiring the weigh, this delay period runs from the weight acquisition and the totalisation.



5.7 Totalisation field

It is possible to define a weight interval (between 0 and the scale capacity) inside of which it is possible to carry out a totalisation and outside of which the totalization is not accepted. Use of the totalling field is particularly useful when totalling is done automatically with the weight stable.

MENU → AF01 functions → Minimum (Maximum) threshold.

5.8 Error messages

Error messages that can be displayed when the totalisation function is executed.

Displayed error message	Type of error	What to do
### 0.015 1 1 1 1 1 1 1 1 1	 The net weight⁽¹⁾ is below the minimum allowed one (20 divisions with approved instrument, zero with non approved instrument) The weight is unstable The net weight⁽¹⁾ is below the minimum threshold or greater than the maximum threshold 	 Load the scale with a weight greater than the minimum allowed one Wait for a stable weight then totalize Load an article with a weight between minimum and maximum thresholds (section 5.7)
4.000 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	The weight hasn't crossed the zero or passed from instability since the last totalisation	Unload the scale then load again

 $[\]overline{}^{(1)}$ In loading mode the net weight must be positive, in unloading or both modes consider the absolute value of the net weight

5.9 Conditions for totalisation

With APPROVED instrument:

- The MANUAL and AUTOMATIC totalisation works with a POSITIVE NET WEIGHT of at least 20 divisions (in LOADING) or a NEGATIVE NET WEIGHT of at least 20 divisions (in UNLOADING)
- For totalisation reenabling see Weighing mode reactivation
- The totalisation excludes the simple printout and viceversa

With NON APPROVED instrument:

- The MANUAL totalisation works with a NET WEIGHT greater than zero (in LOADING) or a NET WEIGHT lower than zero (in UNLOADING)
- The AUTOMATIC totalisation works with a minimum POSITIVE NET WEIGHT of at least 10 divisions (in LOADING) or a NEGATIVE NET WEIGHT of at least 10 divisions (in UNLOADING)
- For totalisation reenabling see Weighing mode reactivation
- The totalisation does not exclude the simple printout

5.10 Progressives

5.10.1 Additional value

In MENU → Progressives → Additional value it's possible to set a value of up to 6 digits, which is summed to each totalisation, and can be recalled in the printing. The same value is linked independently to three total types (PARTIAL, GENERAL, and GRAND TOTAL), in other words, it is possible to print three different values which will be cleared with the clearing of the relative total.

5.10.2 Progressive digits

In MENU progressives Progressive digits it's possible to set the number of digits with which the TICKET PROGRESSIVE and LOT PROGRESSIVE are printed.

The number of settable digits varies from 4 to 16, organised in this way:

- if the actual digits of the total are less than the number of digits set in this step, the difference is filled with some spaces.
- if the actual digits are greater than the number of digits set in this step, only the ones actually entered are taken into consideration (counting from right to left).

The alignment of the total fields is on the left.

NOTE: The number of settable digits DOES NOT INCLUDE the comma.

5.10.3 Ticket progressive

In MENU \rightarrow progressive \rightarrow Ticket progressive, it's possible to modify or clear the TICKET PROGRESSIVE (up to 5 digits).

The TICKET PROGRESSIVE is a progressive number which increments of one upon the first totalisation subsequent to the clearing of the partial total.

5.10.4 Lot progressive

In MENU → Progressive → Lot progressive, one obtains the clearing of the AUTOMATIC LOT (up to 6 digits); before carrying out the actual clearing, one is asked to confirm or cancel the operation.

The AUTOMATIC LOT is a progressive number which increments of one upon the first totalisation subsequent to the clearing of the general total.

DECLARATION OF CONFORMITY

This device conforms to the essential standards and norms relative to the applicable European regulations. The Declaration of conformity is available in the web site www.diniargeo.com.

WARRANTY

The TWO-YEAR warranty period begins on the day the instrument is delivered. It includes spare parts and labour for repairs at no charge if the INSTRUMENTS ARE RETURNED prepaid to the DEALER'S PLACE OF BUSINESS. Warranty covers all defects NOT attributable to the Customer (so are not included in the warranty, failures resulting from improper use) and NOT caused during transport.

If onsite service is requested (or necessary), for any reason, where the instrument is used, the Customer will pay for all of the service technician's costs: travel time and expenses plus room and board (if any).

The customer pays for shipping costs (both ways), if the instrument is shipped to the DEALER or manufacturer for repair.

The WARRANTY is VOIDED if faults occur due to work done by unauthorized personnel or due to connections to equipment installed by others or incorrect connection to the power supply.

This warranty DOES NOT provide for any compensation for losses or damages, direct or indirect, incurred by the Customer due to complete or partial failure of instruments or systems sold, even during the warranty period.

AUTHORISED SERVICE CENTRE STAMP