


MANUAL OCS-SL

Water proof version



Water proof crane scale OCS-SL is re-equip model based on ordinary crane scale OCS-SL. We take out the two keys (ON/OFF, TARE) of the front panel, and put the ON/OFF key on the back panel. On the back panel, the black button is used for recharging battery. The TARE function can be achieved through the TARE key on the remote control. All other function is just as same as ordinary model, please refer our user manual OCS-SL